

is bent resulting in unsightly appearance and performance deficiencies when the trim cap is installed as part of a completed sign and (2) to dimple the trim cap material so that the dimple is visible from both sides of the trim cap material.

II. REMARKS

The foregoing Abstract is submitted in compliance with the Notice to File Missing Parts (Nonprovisional). It is supported by the specification and drawings as filed and does not contain any new matter.


Applicant is unaware of any other amount that is required in connection with this filing.

In the event of any deficiency or of any excess, you are hereby authorized to charge such deficiency or credit such excess to Deposit Account No. 13-2725 with respect to Attorney Docket No. 40203.2USU1.

Respectfully submitted this 25th day of January 2002.



MERCHANT & GOULD, PC


Thomas H. Young
Registration No. 25,796
P.O. Box 2903
Minneapolis, MN 55402-0903
Phone: 303-357-1667

Attorneys for Applicants